

## Ambic Product News

### EasiFoamer™ Manifold Upgrade

An improved design for the EasiFoamer™ applicator is being introduced with immediate effect. The current fixed manifold which screws into the back of the EasiFoamer™ Applicator is being replaced by a Remote Manifold Assembly as shown.



The EasiFoamer™ Coil (AAF/006) will now delivered as follows:



The EasiFoamer™ Manifold Repair Kit (AAF/016) will now delivered as follows:



The part numbers for the Applicator Assembly, Coil and Manifold Repair Kit remain unchanged (AAF/004, AAF/006 & AAF/016).

For further details please contact the Ambic Sales Office as follows:

Lisa Bradley  
Julie Salmon  
Mark Cinderey

[lisabradley@ambic.co.uk](mailto:lisabradley@ambic.co.uk)  
[juliesalmon@ambic.co.uk](mailto:juliesalmon@ambic.co.uk)  
[markcinderey@ambic.co.uk](mailto:markcinderey@ambic.co.uk)

+44 (0) 1993 701937  
+44 (0) 1993 701936  
+44 (0) 7967 483332